

Electronic Resource INC.

Stock List

廠牌	P/N	總計數量
AAVID	529702B02500G	0
ADI	OP275GP	0
ADI	AD620ARE	0
AMD	AM29F040-90JI	10
AMCC	PPC405EX-NSD400T	0
ATMEL	AT24C128BN-SH-T	0
ATMEL	ATTINY2313-20PU	0
BI	82PR5KLF	0
DIODES	MMBZ5232BS-7-F	3000
DIODES	SMBJ33CA	3000
EXAR	SPX3819M5-L-TR	0
FAIRCHILD	MPSA18	5703
FAIRCHILD	BC550BBU	8000
FAIRCHILD	2N4126	0
FAIRCHILD	J177	6000
FAIRCHILD	MM74HC14M	50
FAIRCHILD	MMBT5089	36000
FAIRCHILD	2N3819	8
FAIRCHILD	2N7000	6000
FAIRCHILD	FOD817	5
FAIRCHILD	MMBZ5239B	3000
FAIRCHILD	MMBZ5231B	0
FAIRCHILD	2N7002DW	3000
FAIRCHILD	MMBTA13	0
FAIRCHILD	MMBF177LT1	41000
FAIRCHILD	CD4047BCMX	0
FAIRCHILD	MM74HC123AM	22
FAIRCHILD	DM74ALS05AN	9
FAIRCHILD	TIP126TU	50
FAIRCHILD	6N139	700
FAIRCHILD	FOPF9N90CT	176
FAIRCHILD	LF353N	1455
FAIRCHILD	2N5457	2000
FAIRCHILD	J202	2
FAIRCHILD	MPSA14	5000
FAIRCHILD	2N5952	6000
FAIRCHILD	FFB3906	0
FAIRCHILD	NC7SB3157P6X	18000
FAIRCHILD	2N5087BU	4000
FAIRCHILD	BC546BTA	0
FAIRCHILD	MMBF5434	0
FAIRCHILD	FDS6630A	0
FAIRCHILD	FFB3904	0
FAIRCHILD	BC63916	0

<u>FAIRCHILD</u>	<u>MOC3041M</u>	1000
<u>FAIRCHILD</u>	<u>MMBFJ201</u>	27000
<u>FAIRCHILD</u>	<u>CNY173SM</u>	0
<u>FAIRCHILD</u>	<u>BC550CBU</u>	0
<u>FAIRCHILD</u>	<u>MMBF5457</u>	3000
<u>FAIRCHILD</u>	<u>MMBFJ113</u>	18000
<u>FAIRCHILD/ON</u>	<u>MMBZ5240B</u>	6000
<u>Fairchild / NXP / ON</u>	<u>2N7002</u>	0
<u>FREESCALE / MOTOROLA</u>	<u>MC68HC705C9ACFB</u>	48
<u>FORMOSA MICROSEMI</u>	<u>ZMM55C4V7</u>	2246
<u>FORMOSA MICROSEMI</u>	<u>ZMM55C6V8</u>	2366
<u>FRONTIER ELECTRONIC</u>	<u>M7-TF95-LF</u>	1754
<u>FCS</u>	<u>BC560CBU</u>	0
<u>FCS</u>	<u>74LVTH16373MTDX</u>	1000
<u>IR</u>	<u>IPS1042GPBF</u>	650
<u>IR</u>	<u>IRF3710</u>	500
<u>IR</u>	<u>IRLR120</u>	202
<u>IR</u>	<u>IRF3205</u>	2700
<u>IR</u>	<u>IPS511G</u>	164
<u>IR</u>	<u>IRF7606TRPBF</u>	4000
<u>IR</u>	<u>IRF7822TRPBF</u>	0
<u>INTERSIL</u>	<u>CA3130EZ</u>	0
<u>JRC</u>	<u>NJM78L12UA</u>	0
<u>JRC</u>	<u>NJM78L15UA</u>	0
<u>LTC</u>	<u>LT1086CS8-3.3</u>	229
<u>MILL-MAX</u>	<u>940-44-044-24-000000</u>	4160
<u>MICROCHIP</u>	<u>PIC18LF1220-I/SS</u>	5
<u>MICROCHIP</u>	<u>TC4427EPA</u>	0
<u>MICROCHIP</u>	<u>24LC64T-1/SN</u>	0
<u>MICROCHIP</u>	<u>MCP4561-104E</u>	0
<u>MICREL</u>	<u>MIC2505-2YM</u>	400
<u>MURATA</u>	<u>GRM31C5C1H563JA01</u>	0
<u>MURATA</u>	<u>GRM188F51E105ZA12D</u>	2370
<u>MURATA</u>	<u>GRM31R71C475A01L</u>	1000
<u>MURATA</u>	<u>GRM3195C1H183JA0</u>	0
<u>MURATA</u>	<u>GRM21B5C1H223JA0</u>	6000
<u>MAXIM</u>	<u>MAX1044CSA</u>	5
<u>NXP</u>	<u>BCX56-16</u>	975
<u>NXP</u>	<u>74HC08N</u>	0
<u>NXP</u>	<u>74LVC125AD</u>	0
<u>NXP</u>	<u>BLT81.115</u>	1000
<u>NXP</u>	<u>PESD12VL1BA,115</u>	6000
<u>NXP</u>	<u>BC846B</u>	12000
<u>NXP</u>	<u>HEF4049BT</u>	0
<u>NXP</u>	<u>74LVC2245APW</u>	1254
<u>NXP</u>	<u>HEF4017BP</u>	220
<u>NXP</u>	<u>74HC688</u>	114
<u>NXP</u>	<u>74HC244</u>	110
<u>NXP</u>	<u>74HC08DT</u>	440

<u>NXP</u>	<u>BC848B</u>	<u>3000</u>
<u>NXP</u>	<u>74HC14D.653'</u>	<u>57</u>
<u>NXP</u>	<u>74HC125D</u>	<u>500</u>
<u>NXP</u>	<u>74HC139D</u>	<u>0</u>
<u>NXP</u>	<u>74HC32D</u>	<u>0</u>
<u>NXP</u>	<u>74LVC1G14GV</u>	<u>0</u>
<u>NXP</u>	<u>BZX79-C12AMO</u>	<u>50</u>
<u>NXP</u>	<u>74LVC1G86GV</u>	<u>0</u>
<u>NXP</u>	<u>N74F27N</u>	<u>0</u>
<u>NXP</u>	<u>PMBD914-T</u>	<u>6000</u>
<u>NXP</u>	<u>74LVC1G02GV</u>	<u>0</u>
<u>NXP</u>	<u>P87LPC767BD</u>	<u>1000</u>
<u>NXP</u>	<u>BZX84-C3V0</u>	<u>0</u>
<u>NXP</u>	<u>HEF4011BT</u>	<u>0</u>
<u>NXP</u>	<u>74HC245PW</u>	<u>0</u>
<u>NXP</u>	<u>BC849C-T</u>	<u>0</u>
<u>NXP</u>	<u>HC125PW</u>	<u>0</u>
<u>NXP</u>	<u>BZX384-C33</u>	<u>0</u>
<u>NXP</u>	<u>74HC164DT</u>	<u>0</u>
<u>NSC</u>	<u>DS26LS31CM</u>	<u>10</u>
<u>NSC</u>	<u>1DS26LS32ACM</u>	<u>10</u>
<u>NEC</u>	<u>PS2501-1-ALK</u>	<u>194</u>
<u>NEC</u>	<u>TEESVA1A226M8R</u>	<u>996</u>
<u>NEC</u>	<u>2SB772Q</u>	<u>2000</u>
<u>NEC</u>	<u>2SD596</u>	<u>0</u>
<u>N.S.</u>	<u>LM2623MM/NOPB</u>	<u>5</u>
<u>NS</u>	<u>TL064CN</u>	<u>0</u>
<u>NS</u>	<u>LM78L05ACMX</u>	<u>5</u>
<u>NS</u>	<u>LM833N/NOPB</u>	<u>0</u>
<u>NS</u>	<u>LM9061M</u>	<u>65</u>
<u>NS</u>	<u>LP2951CM</u>	<u>50</u>
<u>NS</u>	<u>LM338T/NOPB</u>	<u>8</u>
<u>NS</u>	<u>ADC0820CCN</u>	<u>0</u>
<u>NS</u>	<u>LM13700MX</u>	<u>0</u>
<u>NS</u>	<u>LM1117MPX-3.3</u>	<u>2000</u>
<u>NSC</u>	<u>LF442CN/NOPB</u>	<u>1600</u>
<u>NSC</u>	<u>LM3578AMXNOPB</u>	<u>0</u>
<u>NJR</u>	<u>NJM13600D</u>	<u>0</u>
<u>ON</u>	<u>MC78L15ACDG</u>	<u>33</u>
<u>ON</u>	<u>BC847CLT1G</u>	<u>6985</u>
<u>ON</u>	<u>BAV99LT1G</u>	<u>5977</u>
<u>ON</u>	<u>BAW56LT1G</u>	<u>2950</u>
<u>ON</u>	<u>MMBTH10LT1G</u>	<u>1755</u>
<u>ON</u>	<u>MC78L05ACDR2G</u>	<u>0</u>
<u>ON</u>	<u>MC33174DR2G</u>	<u>2125</u>
<u>ON</u>	<u>MC33179DR2G</u>	<u>7500</u>
<u>ON</u>	<u>MC14585BDR2G</u>	<u>0</u>
<u>ON</u>	<u>MC14584BD</u>	<u>0</u>
<u>ON</u>	<u>MMBT5088</u>	<u>36000</u>

<u>ON</u>	<u>MC100EPT23DTR2</u>	<u>833</u>
<u>ON</u>	<u>MBRS330T3G</u>	<u>0</u>
<u>ON</u>	<u>BCP53T1G</u>	<u>7000</u>
<u>ON</u>	<u>BC847BLT1G</u>	<u>3000</u>
<u>ON</u>	<u>MMBTA06LT1G</u>	<u>0</u>
<u>ON</u>	<u>MMBTA14</u>	<u>0</u>
<u>ON</u>	<u>1N5374BG</u>	<u>2000</u>
<u>ON</u>	<u>MMBT2222LT1G</u>	<u>3000</u>
<u>ON</u>	<u>MBRS1100T3G</u>	<u>2500</u>
<u>ON</u>	<u>MBR0520LT1G</u>	<u>42</u>
<u>ON</u>	<u>MC14017BCPG</u>	<u>110</u>
<u>ON</u>	<u>MC33274AP</u>	<u>800</u>
<u>ON</u>	<u>LM339DR2G</u>	<u>0</u>
<u>ON</u>	<u>MBRS130T3G</u>	<u>10000</u>
<u>ON</u>	<u>MC14584BCP</u>	<u>100</u>
<u>ON</u>	<u>NCP1203D60R2</u>	<u>0</u>
<u>ON</u>	<u>1N5347BRLG</u>	<u>0</u>
<u>ON</u>	<u>1N5349BRLG</u>	<u>0</u>
<u>ON</u>	<u>MC14584BDTR2G</u>	<u>0</u>
<u>ON</u>	<u>MMUN2212LT1G</u>	<u>0</u>
<u>ON</u>	<u>1SMB5943BT3G</u>	<u>20</u>
<u>ON</u>	<u>LM239DG</u>	<u>0</u>
<u>ON</u>	<u>MMBT5087LT1G</u>	<u>3000</u>
<u>ON</u>	<u>SD12CT1G</u>	<u>6000</u>
<u>ON</u>	<u>NUD4001DR2G</u>	<u>0</u>
<u>ON</u>	<u>MC78L09ACDG</u>	<u>0</u>
<u>ON</u>	<u>MC33171DR2G</u>	<u>0</u>
<u>ON</u>	<u>MC14049BDR2G</u>	<u>0</u>
<u>ON</u>	<u>MC33178DR2G</u>	<u>5000</u>
<u>ON</u>	<u>MC33178PG</u>	<u>0</u>
<u>ON</u>	<u>2N7002LT1G</u>	<u>0</u>
<u>ON</u>	<u>MC14028BDR2G</u>	<u>0</u>
<u>ON</u>	<u>MC14175BDR2G</u>	<u>0</u>
<u>ON</u>	<u>MC14532BDG</u>	<u>0</u>
<u>ON</u>	<u>MC14077BDG</u>	<u>1155</u>
<u>ON</u>	<u>LM2931CDR2G</u>	<u>1000</u>
<u>PH</u>	<u>74HC240</u>	<u>761</u>
<u>PH</u>	<u>74HCT193D</u>	<u>100</u>
<u>PH</u>	<u>74HC154D</u>	<u>3490</u>
<u>PH</u>	<u>74HC273N</u>	<u>1440</u>
<u>PANASONIC</u>	<u>ECJ2FF1A106Z</u>	<u>984</u>
<u>PANASONIC</u>	<u>ECJ1VF1A105Z</u>	<u>688</u>
<u>PANASONIC</u>	<u>MN3208</u>	<u>6</u>
<u>PANASONIC</u>	<u>ELL-6SH470N</u>	<u>0</u>
<u>PANASONIC</u>	<u>ECH-U1H333GX5</u>	<u>2000</u>
<u>PANASONIC</u>	<u>ECH-U1H683JX9</u>	<u>0</u>
<u>PANASONIC</u>	<u>ECH-U1C104GX5</u>	<u>2000</u>
<u>PHILIPS</u>	<u>PH2369</u>	<u>0</u>
<u>PHILIPS</u>	<u>HEF4046BP</u>	<u>5</u>

<u>PHILIPS</u>	<u>BAS28</u>	<u>0</u>
<u>PHILIPS</u>	<u>BAV21</u>	<u>0</u>
<u>PHILIPS</u>	<u>BC868</u>	<u>0</u>
<u>PHILIPS</u>	<u>HEF4047BT</u>	<u>0</u>
<u>PHILIPS/RS/NXP</u>	<u>BZX384-C12</u>	<u>0</u>
<u>ROHM</u>	<u>UMX1NTN</u>	<u>0</u>
<u>ROHM</u>	<u>UMZ1NTR</u>	<u>0</u>
<u>ST</u>	<u>1.5KE33CA</u>	<u>0</u>
<u>ST</u>	<u>M29W160EB70N6F</u>	<u>0</u>
<u>ST</u>	<u>1.5KE6V8CA</u>	<u>7400</u>
<u>ST</u>	<u>NE556N</u>	<u>50</u>
<u>ST</u>	<u>STPR820D</u>	<u>45</u>
<u>ST</u>	<u>M25P16-VMN6TP</u>	<u>0</u>
<u>ST</u>	<u>BAT46</u>	<u>500</u>
<u>ST</u>	<u>BYT01-400'</u>	<u>40</u>
<u>ST</u>	<u>74ACT02B</u>	<u>100</u>
<u>ST</u>	<u>SA555DT</u>	<u>0</u>
<u>ST</u>	<u>UA741CN</u>	<u>0</u>
<u>STM</u>	<u>BUX48A</u>	<u>0</u>
<u>SLR</u>	<u>LR8K4-G</u>	<u>0</u>
<u>FAIRCHILD</u>	<u>FOD817D</u>	<u>5</u>
<u>TI</u>	<u>NE555DRG4</u>	<u>50</u>
<u>TI</u>	<u>CD4016BE</u>	<u>400</u>
<u>TI</u>	<u>TLC2252CDR</u>	<u>0</u>
<u>TI</u>	<u>SN74LVC1G32DBVR</u>	<u>0</u>
<u>TI</u>	<u>CD4069UBM</u>	<u>5</u>
<u>TI</u>	<u>MAX232N</u>	<u>0</u>
<u>TI</u>	<u>SN74LVC1G32DBV</u>	<u>0</u>
<u>TI</u>	<u>TL061CDR</u>	<u>5000</u>
<u>TI</u>	<u>TPS5410D</u>	<u>5</u>
<u>TI</u>	<u>MSP430F5436IPZ</u>	<u>2</u>
<u>TI</u>	<u>SN74LVTH16245ADL</u>	<u>99</u>
<u>TI</u>	<u>TL061CP</u>	<u>5000</u>
<u>TI</u>	<u>CD4070BE</u>	<u>400</u>
<u>TI</u>	<u>TL022CP</u>	<u>500</u>
<u>TI</u>	<u>1SN74LVTH162244D</u>	<u>501</u>
<u>TI</u>	<u>TLC2264CDR</u>	<u>0</u>
<u>TI</u>	<u>UA741CDR</u>	<u>4652</u>
<u>TI</u>	<u>CD4093BM</u>	<u>0</u>
<u>TI</u>	<u>TL074CDR</u>	<u>2500</u>
<u>TI</u>	<u>SN74LVTH16373DLR</u>	<u>1132</u>
<u>TI</u>	<u>CD4099BE</u>	<u>300</u>
<u>TI</u>	<u>PCM2900E</u>	<u>5</u>
<u>TI</u>	<u>TLC2262CD</u>	<u>10</u>
<u>TI</u>	<u>SN74LVC2G08DCUR</u>	<u>100</u>
<u>TI</u>	<u>SN74LV2G07DCKRG4</u>	<u>200</u>
<u>TI</u>	<u>SN74LVC1G00DCK</u>	<u>500</u>
<u>TI</u>	<u>TL051CP</u>	<u>0</u>
<u>TI</u>	<u>UA78L02ACLP</u>	<u>0</u>

<u>TI</u>	LP2951-50D	<u>0</u>
<u>TI</u>	RC4558DR	<u>0</u>
<u>TI</u>	LM393DR	<u>0</u>
<u>TI</u>	TPS61222DCKT	<u>0</u>
<u>TI</u>	OP07CDR	<u>2500</u>
<u>TI</u>	SN74LVC3G07DCUR	<u>0</u>
<u>TOS</u>	ULN2803AFWG	<u>4000</u>
<u>TOSHIBA</u>	2SC2712-GR	<u>1736</u>
<u>TOSHIBA</u>	TLP283(F)	<u>1600</u>
<u>TOSHIBA</u>	ULN2004AFWG	<u>16</u>
<u>TYCO</u>	7-215460-6	<u>0</u>
<u>TYCO</u>	IMO5CGR	<u>0</u>
<u>TYCO</u>	770602-6	<u>0</u>
<u>VISHAY</u>	SD103A	<u>0</u>
<u>VISHAY</u>	SMCJ6.5CA/57T	<u>0</u>
<u>VISHAY</u>	SI2301BDS-T1-E3'	<u>12000</u>
<u>VISHAY</u>	593D686X9020E2T	<u>260</u>
<u>VISHAY</u>	DG409DJ-E3	<u>0</u>
<u>VISHAY</u>	50SQ100	<u>0</u>
<u>VISHAY</u>	IRF9240PBF	<u>0</u>
<u>VISHAY</u>	CCF6068K1FKE36	<u>10</u>
<u>VISHAY</u>	30WQ03FNPBF	<u>0</u>
<u>WALSIN</u>	0603F474Z250CT	<u>990</u>
<u>WALSIN</u>	1206B225K250CT	<u>980</u>
<u>WALSIN</u>	0805N1R0C500LT	<u>3604</u>
<u>WALSIN</u>	0805N1R5C500LT	<u>992</u>
<u>XILINX</u>	XC2C128-7VOG100I	<u>0</u>
<u>YAGEO</u>	CC0603KRX7R9BB103	<u>405</u>
<u>YAGEO</u>	CC1206KRX7R9BB104	<u>996</u>
<u>YAGEO</u>	CC0603ZRY5V6BB225	<u>1994</u>
<u>YAGEO</u>	CC0603JRNPO9BN391	<u>1417</u>
<u>YAGEO</u>	CC0603KRX7R9BB472	<u>4553</u>
<u>YAGEO</u>	RC1206FR-0720RL	<u>3995</u>
<u>YAGEO</u>	RC0603FR-0739RL	<u>2992</u>
<u>YAGEO</u>	RC0603FR-0751RL	<u>347</u>
<u>YAGEO</u>	RC0603FR-07100R	<u>1748</u>
<u>YAGEO</u>	RC0603FR-07200RL	<u>4811</u>
<u>YAGEO</u>	RC0603FR-07220RL	<u>4588</u>
<u>YAGEO</u>	RC0603FR-07910RL	<u>1990</u>
<u>YAGEO</u>	RC0805FR-071KL	<u>1950</u>
<u>YAGEO</u>	RC0603FR-071KL	<u>4530</u>
<u>YAGEO</u>	RC0603FR-071K2L	<u>4270</u>
<u>YAGEO</u>	RC0603FR-072K2L	<u>4412</u>
<u>YAGEO</u>	RC0603FR-072K4L	<u>1717</u>
<u>YAGEO</u>	RC0603FR-073KL	<u>240</u>
<u>YAGEO</u>	RC0603FR-073K3L	<u>3980</u>
<u>YAGEO</u>	RC0805FR-073K6L	<u>1993</u>
<u>YAGEO</u>	RC0603FR-073K9	<u>3580</u>
<u>YAGEO</u>	RC0603FR-075K1L	<u>4143</u>

<u>YAGEO</u>	<u>RC0603FR-0710KL</u>	<u>675</u>
<u>YAGEO</u>	<u>RC0603FR-0720KL</u>	<u>2556</u>
<u>YAGEO</u>	<u>RC0603FR-0722KL</u>	<u>4080</u>
<u>YAGEO</u>	<u>RC0603FR-0747K</u>	<u>2757</u>
<u>YAGEO</u>	<u>RC0603FR-07240KL</u>	<u>4640</u>
<u>YAGEO</u>	<u>RC0603FR-07300KL</u>	<u>4363</u>
<u>YAGEO</u>	<u>RC0603FR-071M2L</u>	<u>4473</u>
<u>YAGEO</u>	<u>CC0805JRNPO9BN470</u>	<u>3358</u>
<u>YAGEO</u>	<u>CC0805JRNPO9BN391</u>	<u>627</u>
<u>YAGEO</u>	<u>CC1206ZRY5V9BB474</u>	<u>3725</u>
<u>YAGEO</u>	<u>RC0603FR-0720RL</u>	<u>2370</u>
<u>YAGEO</u>	<u>RC0603FR-071K8L</u>	<u>2507</u>
<u>YAGEO</u>	<u>RC0603FR-073K6L</u>	<u>2390</u>
<u>YAGEO</u>	<u>RC0603FR-078K2L</u>	<u>2578</u>
<u>YAGEO</u>	<u>RC0603FR-0730KL</u>	<u>3040</u>
<u>YENYO</u>	<u>LL4148</u>	<u>60</u>
<u>YENYO</u>	<u>SS16</u>	<u>3000</u>
<u>ZETEX</u>	<u>BS250P</u>	<u>4075</u>
<u>NJR</u>	<u>NJM2920M(TE1)</u>	<u>857</u>
<u>WALSIN 華新科(信昌)</u>	<u>0805B104K500CT</u>	<u>61</u>
<u>WALSIN 華新科(信昌)</u>	<u>0603B104K500CT</u>	<u>3377</u>
<u>WALSIN 華新科(信昌)</u>	<u>0805N1R2C500LT</u>	<u>3714</u>
<u>WALSIN 華新科(信昌)</u>	<u>0603B472K500CT</u>	<u>553</u>
<u>WALSIN 華新科(信昌)</u>	<u>0603N1R2C500LT</u>	<u>980</u>
<u>WALSIN 華新科(信昌)</u>	<u>0603N2R4C500LT</u>	<u>957</u>
<u>WALSIN 華新科(信昌)</u>	<u>0603N470J500LT</u>	<u>1981</u>
<u>WALSIN 華新科(信昌)</u>	<u>0603N1R0C500LT</u>	<u>993</u>
<u>新電元</u>	<u>2SD1795</u>	<u>2000</u>
<u>0</u>	<u>TLC431CDR</u>	<u>10</u>
<u>0</u>	<u>SN74HC00DR</u>	<u>5</u>
<u>0</u>	<u>TLP181GBTPRFT</u>	<u>50</u>
<u>0</u>	<u>LF444CM</u>	<u>100</u>
<u>0</u>	<u>LM13700M</u>	<u>8</u>
<u>0</u>	<u>P9NK50ZFP</u>	<u>35</u>
<u>0</u>	<u>SN74LVC2G04DCKR</u>	<u>100</u>
<u>0</u>	<u>PIC16LF722-I-SS</u>	<u>0</u>
<u>0</u>	<u>BAV99W</u>	<u>0</u>
<u>0</u>	<u>BZX85C3V3-T50R</u>	<u>0</u>
<u>0</u>	<u>MMBT5962</u>	<u>0</u>
<u>0</u>	<u>FDS6690A</u>	<u>0</u>
<u>0</u>	<u>MC74AC573N</u>	<u>0</u>
<u>0</u>	<u>NDS9435A</u>	<u>0</u>
<u>0</u>	<u>SN74LVC2G07DCKRG4</u>	<u>0</u>
<u>0</u>	<u>AD633JRZ</u>	<u>0</u>

Electronic Resource INC.

Stock List

廠牌	P/N	總計數量
----	-----	------

0	PN2484	0
0	MMDT3946-7-F	3000
0	CD74HC4053M96	0
0	1SMA5914BT3G	8974
0	UA78L09ACLP	500
0	1N5236B	0
0	HCF4093BEY	0
0	J113	0
0	LM324N	0
0	TLV274ID	0
0	BAV70	0
0	SN74LVTH16245MTDX	0
0	KSD471ACYBU	0
0	HCT251N	0
0	MC14016BDG	0
0	74HC191D	0
0	TSC2200IRHBR	0
0	74HC04D	500
0	ATMEGA645V	0
0	SN75176BDR	0
0	M74HC237M	0
0	TPS5430DDAR	0
0	AD797ANZ	0
0	PIC16C55A	0
0	IPS6021SPBF	0
0	MMBT2369ACT	0
0	74HC175N	0
0	LM7824CT	0
0	LM2577S-ADJ	0
0	UA78L10ACLP	0
0	CNY17F-3	0
0	NGB8202NT4G	0
0	STS4DNE60L	0
0	BAS70-04-7-F	0
0	SST39VF6401B-70-4C-E-KE	0
0	MC33172DR2G	0
0	FAN4803CP	0
0	ISP1583BS	5000
0	MCP73833	0
0	ISL88002IH26Z	0
0	IRFS3306PBF	0
0	SN74LVC2G06DCKR	0
0	MMBT4126	0
0	TLE4208G	0
0	L7805CP	500
0	TL082CDT	2500
AMD	1	10
AMD	1	10
AMD	1	10

